

- Preface p. v
- 1. Causes of Noise p. 1
 - 1.1 Possible causes of gear noise p. 1
 - 1.2 The basic idea of Transmission Error p. 3
 - 1.3 Gearbox internal responses p. 6
 - 1.4 External responses p. 8
 - 1.5 Overall path to noise p. 8
 - 1.6 T.E.-noise relationship p. 9
 - References p. 11
- 2. Harris Mapping for Spur Gears p. 13
 - 2.1 Elastic deflections of gears p. 13
 - 2.2 Reasons for tip relief p. 15
 - 2.3 Unloaded T.E. for spur gears p. 19
 - 2.4 Effect of load on T.E. p. 21
 - 2.5 Long, short or intermediate relief p. 23
 - References p. 25
- 3. Theoretical Helical Effects p. 27
 - 3.1 Elastic averaging of T.E. p. 27
 - 3.2 Loading along contact line p. 29
 - 3.3 Axial forces p. 31
 - 3.4 Position variation p. 31
 - 3.5 "Friction reversal" and "contact shock" effects p. 33
 - 3.6 No-load condition p. 35
 - References p. 35
- 4. Prediction of Static T.E. p. 37
 - 4.1 Possibilities and problems p. 37
 - 4.2 Thin slice assumptions p. 38
 - 4.3 Tooth shape assumptions p. 40
 - 4.4 Method of approach p. 44
 - 4.5 Program with results p. 48
 - 4.6 Accuracy of estimates and assumptions p. 53
 - 4.7 Design options for low noise p. 58
 - References p. 59
- 5. Prediction of Dynamic Effects p. 61
 - 5.1 Modelling of gears in 2-D p. 61
 - 5.2 Time marching approach p. 64
 - 5.3 Starting conditions p. 65
 - 5.4 Dynamic program p. 66
 - 5.5 Stability and step length p. 71
 - 5.6 Accuracy of assumptions p. 73
 - 5.7 Sound predictions p. 75
 - References p. 76
- 6. Measurements p. 77
 - 6.1 What to measure p. 77
 - 6.2 Practical measurements p. 79
 - 6.3 Calibrations p. 84

- 6.4 Measurement of internal resonances p. 85
- 6.5 Measurement of external resonances p. 87
- 6.6 Isolator transmission p. 88
- 6.7 Once per revolution marker p. 90
- References p. 92
- 7. Transmission Error Measurement p. 93
- 7.1 Original approach p. 93
- 7.2 Batching approach p. 95
- 7.3 Velocity approach p. 96
- 7.4 High speed approach p. 99
- 7.5 Tangential accelerometers p. 103
- 7.6 Effect of dynamics p. 104
- 7.7 Choice of encoders p. 106
- 7.8 Accuracy of measurement p. 110
- 7.9 Worms and wheels and spiral bevels p. 112
- 7.10 Practical problems p. 113
- 7.11 Comparisons p. 117
- References p. 119
- 8. Recording and Storage p. 121
- 8.1 Is recording required? p. 121
- 8.2 Digital v. analog p. 122
- 8.3 Current PC limits p. 123
- 8.4 Form of results p. 124
- 8.5 Aliasing and filters p. 127
- 8.6 Information compression p. 132
- 8.7 Archive information p. 136
- References p. 137
- 9. Analysis Techniques p. 139
- 9.1 Types of noise and irritation p. 139
- 9.2 Problem identification p. 140
- 9.3 Frequency analysis techniques p. 142
- 9.4 Window effects and bandwidth p. 148
- 9.5 Time averaging and jitter p. 152
- 9.6 Average or difference p. 157
- 9.7 Band and line filtering and re-synthesis p. 158
- 9.8 Modulation p. 161
- 9.9 Pitch effects p. 163
- 9.10 Phantoms p. 165
- References p. 166
- 10. Improvements p. 167
- 10.1 Economics p. 167
- 10.2 Improving the structure p. 169
- 10.3 Improving the isolation p. 171
- 10.4 Reducing the T.E. p. 174
- 10.5 Permissible T.E. levels p. 175
- 10.6 Frequency changing p. 178

- 10.7 Damping p. 179
- 10.8 Production control options p. 181
- References p. 183
- 11. Lightly Loaded Gears p. 185
- 11.1 Measurement problems p. 185
- 11.2 Effects and identification p. 187
- 11.3 Simple predictions p. 189
- 11.4 Possible changes p. 192
- 11.5 Anti-backlash gears p. 193
- 11.6 Modelling rattle p. 194
- Reference p. 200
- 12. Planetary and Split Drives p. 201
- 12.1 Design philosophies p. 201
- 12.2 Advantages and disadvantages p. 203
- 12.3 Excitation phasing p. 205
- 12.4 Excitation frequencies p. 208
- 12.5 T.E. testing p. 209
- 12.6 Unexpected frequencies p. 210
- Reference p. 213
- 13. High Contact Ratio Gears p. 215
- 13.1 Reasons for interest p. 215
- 13.2 Design with Harris maps p. 216
- 13.3 2 stage relief p. 217
- 13.4 Comparisons p. 218
- 13.5 Measurement of T.E. p. 219
- References p. 222
- 14. Low Contact Ratio Gears p. 223
- 14.1 Advantages p. 223
- 14.2 Disadvantages p. 227
- 14.3 Curvature problems p. 227
- 14.4 Frequency gains p. 229
- 15. Condition Monitoring p. 231
- 15.1 The problem p. 231
- 15.2 Not frequency analysis p. 232
- 15.3 Averaging or not p. 233
- 15.4 Damage criteria p. 234
- 15.5 Line elimination p. 237
- 15.6 Scuffing - Smith Shocks p. 238
- 15.7 Bearing signals p. 241
- References p. 243
- 16. Vibration Testing p. 245
- 16.1 Objectives p. 245
- 16.2 Hydraulic vibrators p. 249
- 16.3 Hammer measurements p. 250
- 16.4 Reciprocal theorem p. 254
- 16.5 Sweep, impulse, noise or chirp p. 255

- 16.6 Combining results p. 257
- 16.7 Coherence p. 260
- 17. Couplings p. 263
- 17.1 Advantages p. 263
- 17.2 Problems p. 264
- 17.3 Vibration generation p. 266
- 18. Failures p. 269
- 18.1 Connection with vibration p. 269
- 18.2 Pitting p. 269
- 18.3 Micropitting p. 270
- 18.4 Cracking p. 271
- 18.5 Scuffing p. 272
- 18.6 Bearings p. 273
- 18.7 Debris detection p. 276
- 18.8 Couplings p. 277
- 18.9 Loadings p. 278
- 18.10 Overheating p. 279
- References p. 280
- 19. Strength v. Noise p. 281
- 19.1 The connection between strength and noise p. 281
- 19.2 Design for low noise helicals p. 282
- 19.3 Design sensitivity p. 285
- 19.4 Buying problems p. 286
- Units p. 289
- Index p. 291