

- Preface
- Contents
- 1 Induction Machines: An Introduction p. 1
  - 1.1 Electric Energy and Induction Motors p. 1
  - 1.2 A Historical Touch p. 2
  - 1.3 Induction Machines in Applications p. 4
  - 1.4 Conclusion p. 14
  - 1.5 References p. 14
- 2 Construction Aspects and Operation Principles p. 15
  - 2.1 Construction Aspects of Rotary IMs p. 16
  - 2.2 Construction Aspects of Linear Induction Motors p. 26
  - 2.3 Operation Principles of IMs p. 29
  - 2.4 Summary p. 33
  - 2.5 References p. 35
- 3 Magnetic, Electric, and Insulation Materials for IM p. 37
  - 3.1 Introduction p. 37
  - 3.2 Soft Magnetic Materials p. 37
  - 3.3 Core (Magnetic) Losses p. 41
  - 3.4 Electrical Conductors p. 46
  - 3.5 Insulation Materials p. 48
  - 3.6 Summary p. 51
  - 3.7 References p. 51
- 4 Induction Machine Windings And Their M.M.Fs p. 55
  - 4.1 Introduction p. 55
  - 4.2 The Ideal Traveling M.M.F. of A.C. Windings p. 55
  - 4.3 A Primitive Single-Layer Winding p. 58
  - 4.4 A Primitive Two-Layer Chorded Winding p. 60
  - 4.5 The mmf Harmonics For Integer Q p. 61
  - 4.6 Rules For Designing Practical A.C. Windings p. 65
  - 4.7 Basic Fractional Q Three-Phase A.C. Windings p. 73
  - 4.8 Basic Pole-Changing Three-Phase A.C. Windings p. 76
  - 4.9 Two-Phase A.C. Windings p. 79
  - 4.10 Pole-Changing With Single-Phase Supply Induction Motors p. 84
  - 4.11 Special Topics On A.C. Windings p. 84
  - 4.12 The mmf of Rotor Windings p. 92
  - 4.13 The "Skewing" mmf Concept p. 93
  - 4.14 Summary p. 94
  - 4.15 References p. 96
- 5 The Magnetization Curve and Inductance p. 99
  - 5.1 Introduction p. 99
  - 5.2 Equivalent Airgap to Account for Slotting p. 100
  - 5.3 Effective Stack Length p. 103
  - 5.4 The Basic Magnetisation Curve p. 104
  - 5.5 The Emf in An A.C. Winding p. 126
  - 5.6 The Magnetization Inductance p. 130
  - 5.7 Summary p. 133

- 5.8 References p. 135
- 6 Leakage Inductances and Resistances p. 137
- 6.1 Leakage Fields p. 137
- 6.2 Differential Leakage Inductances p. 138
- 6.3 Rectangular Slot Leakage Inductance/Single Layer p. 142
- 6.4 Rectangular Slot Leakage Inductance/Two Layers p. 144
- 6.5 Rounded Shape Slot Leakage Inductance/Two Layers p. 146
- 6.6 Zig-Zag Airgap Leakage Inductances p. 148
- 6.7 End-Connection Leakage Inductance p. 150
- 6.8 Skewing Leakage Inductance p. 151
- 6.9 Rotor Bar and End Ring Equivalent Leakage Inductance p. 152
- 6.10 Basic Phase Resistance p. 152
- 6.11 The Cage Rotor Resistance p. 153
- 6.12 Simplified Leakage Saturation Corrections p. 156
- 6.13 Reducing the Rotor to Stator p. 158
- 6.14 Summary p. 160
- 6.15 References p. 162
- 7 Steady State Equivalent Circuit and Performance p. 163
- 7.1 Basic Steady-State Equivalent Circuit p. 163
- 7.2 Classification of Operation Modes p. 166
- 7.3 Ideal No-Load Operation p. 167
- 7.4 Short-Circuit (Zero Speed) Operation p. 170
- 7.5 No-Load Motor Operation p. 175
- 7.6. The Motor Mode of Operation p. 178
- 7.7 Generating to Power Grid p. 179
- 7.8 Autonomous Induction Generator Mode p. 181
- 7.9 The Electromagnetic Torque p. 184
- 7.10 Efficiency and Power Factor p. 190
- 7.11 Phasor Diagrams: Standard and New p. 193
- 7.12 Alternative Equivalent Circuits p. 197
- 7.13 Unbalanced Supply Voltages p. 200
- 7.14 One Stator Phase is Open p. 203
- 7.15 Unbalanced Rotor Windings p. 207
- 7.16 One Rotor Phase is Open p. 209
- 7.17 When Voltage Varies Around Rated Value p. 210
- 7.18 Summary p. 211
- 7.19 References p. 213
- 8 Starting and Speed Control Methods p. 215
- 8.1 Starting of Cage-Rotor Induction Motors p. 215
- 8.2 Starting of Wound-Rotor Induction Motors p. 224
- 8.3 Speed Control Methods for Cage-Rotor Induction Motors p. 227
- 8.4 Variable Frequency Methods p. 230
- 8.5 Speed Control Methods for Wound Rotor Ims p. 240
- 8.6 Summary p. 246
- 8.7 References p. 248
- 9 Skin and On--Load Saturation Effects p. 249

- 9.1 Introduction p. 249
- 9.2 The Skin Effect p. 252
- 9.3 Skin Effects By The Multilayer Approach p. 262
- 9.4 Skin Effect in the End Rings via The Multilayer Approach p. 269
- 9.5 The Double Cage Behaves Like a Deep Bar Cage p. 270
- 9.6 Leakage Flux Path Saturation-A Simplified Approach p. 272
- 9.7 Leakage Saturation And Skin Effects-A Comprehensive Analytical Approach p. 276
- 9.8 The FEM Approach p. 291
- 9.9 Performance of Induction Motors With Skin Effect p. 292
- 9.10 Summary p. 294
- 9.11 References p. 295
- 10 Airgap Field Space Harmonics, Parasitic Torques, Radial Forces, and Noise p. 297
- 10.1 Stator mmf Produced Airgap Flux Harmonics p. 297
- 10.2 Airgap Field of A Squirrel Cage Winding p. 299
- 10.3 Airgap Conductance Harmonics p. 299
- 10.4 Leakage Saturation Influence on Airgap Conductance p. 301
- 10.5 Main Flux Saturation Influence on Airgap Conductance p. 302
- 10.6 The Harmonics-Rich Airgap Flux Density p. 303
- 10.7 The Eccentricity Influence on Airgap Magnetic Conductance p. 303
- 10.8 Interactions of Mmf (or Step) Harmonics and Airgap Magnetic Conductance Harmonics p. 305
- 10.9 Parasitic Torques p. 307
- 10.10 Radial Forces and Electromagnetic Noise p. 322
- 10.11 Summary p. 329
- 10.12 References p. 332
- 11 Losses in Induction Machines p. 335
- 11.1 Loss Classifications p. 336
- 11.2 Fundamental Electromagnetic Losses p. 336
- 11.3 No-Load Space Harmonics (Stray No-Load) Losses in Nonskewed IMs p. 339
- 11.4 Load Space Harmonics (Stray Load) Losses in Nonskewed IMs p. 349
- 11.5 Flux Pulsation (Stray) Losses in Skewed Insulated Bars p. 353
- 11.6 Interbar Current Losses in Noninsulated Skewed Rotor Cages p. 354
- 11.7 No-Load Rotor Skewed Noninsulated Cage Losses p. 361
- 11.8 Load Rotor Skewed Noninsulated Cage Losses p. 361
- 11.9 Rules to Reduce Full Load Stray (Space Harmonics) Losses p. 362
- 11.10 High Frequency Time Harmonics Losses p. 364
- 11.11 Computation of Time Harmonics Conductor Losses p. 369
- 11.12 Time Harmonics Interbar Rotor Current Losses p. 371
- 11.13 Computation of Time Harmonics Core Losses p. 374
- 11.14 Loss Computation by Fem p. 377
- 11.15 Summary p. 380
- 11.16 References p. 382
- 12 Thermal Modeling and Cooling p. 385
- 12.1 Introduction p. 385
- 12.2 Some Air Cooling Methods for IMs p. 386
- 12.3 Conduction Heat Transfer p. 388

- 12.4 Convection Heat Transfer p. 391
- 12.5 Heat Transfer by Radiation p. 392
- 12.6 Heat Transport (Thermal Transients) in a Homogenous Body p. 394
- 12.7 Induction Motor Thermal Transients at Stall p. 395
- 12.8 Intermittent Operation p. 397
- 12.9 Temperature Rise ( $T_{\text{on}}$ ) and Fall ( $T_{\text{off}}$ ) Times p. 399
- 12.9 More Realistic Thermal Equivalent Circuits for IMs p. 400
- 12.10 A Detailed Thermal Equivalent Circuit for Transients p. 404
- 12.11 Thermal Equivalent Circuit Identification p. 405
- 12.12 Thermal Analysis Through FEM p. 408
- 12.13 Summary p. 410
- 12.14 References p. 411
- 13 Induction Machine Transients p. 413
- 13.1 Introduction p. 413
- 13.2 The Phase Coordinate Model p. 413
- 13.3 The Complex Variable Model p. 416
- 13.4 Steady-State by The Complex Variable Model p. 420
- 13.5 Equivalent Circuits for Drives p. 422
- 13.6 Electrical Transients with Flux Linkages as Variables p. 426
- 13.7 Including Magnetic Saturation in The Space Phasor Model p. 428
- 13.8 Saturation and Core Loss Inclusion into The State-Space Model p. 431
- 13.9 Reduced Order Models p. 438
- 13.10 The Sudden Short-Circuit at Terminals p. 446
- 13.11 Most Severe Transients (so far) p. 450
- 13.12 The abc-dq Model for PWM Inverter Fed IMs p. 454
- 13.13 First Order Models Of IMs for Steady-State Stability in Power Systems p. 459
- 13.14 Multimachine Transients p. 462
- 13.15 Subsynchronous Resonance (SSR) p. 464
- 13.16 The M/N<sub>r</sub> Actual Winding Modeling for Transients p. 468
- 13.17 Summary p. 475
- 13.18 References p. 478
- 14 Motor Specifications and Design Principles p. 481
- 14.1 Introduction p. 481
- 14.2 Typical Load Shaft Torque/Speed Envelopes p. 481
- 14.3 Derating p. 485
- 14.4 Voltage and Frequency Variation p. 486
- 14.5 Induction Motor Specifications for Constant V/F p. 487
- 14.6 Matching IMs to Variable Speed/Torque Loads p. 491
- 14.7 Design Factors p. 493
- 14.8 Design Features p. 494
- 14.9 The Output Coefficient Design Concept p. 496
- 14.10 The Rotor Tangential Stress Design Concept p. 503
- 14.11 Summary p. 506
- 14.12 References p. 508
- 15 IM Design Below 100 kW and Constant V and f p. 509
- 15.1 Introduction p. 509

- 15.2 Design Specifications by Example p. 510
- 15.3 The Algorithm p. 510
- 15.4 Main Dimensions of Stator Core p. 512
- 15.5 The Stator Winding p. 513
- 15.6 Stator Slot Sizing p. 517
- 15.7 Rotor Slots p. 521
- 15.8 The Magnetization Current p. 525
- 15.9 Resistances and Inductances p. 526
- 15.10 Losses and Efficiency p. 532
- 15.11 Operation Characteristics p. 535
- 15.12 Temperature Rise p. 536
- 15.13 Summary p. 538
- 15.14 References p. 539
- 16 Induction Motor Design Above 100kW and Constant V/f p. 541
- 16.1 Introduction p. 541
- 16.2 High Voltage Stator Design p. 544
- 16.3 Low Voltage Stator Design p. 551
- 16.4 Deep Bar Cage Rotor Design p. 552
- 16.5 Double Cage Rotor Design p. 559
- 16.6 Wound Rotor Design p. 566
- 16.7 IM with Wound Rotor-Performance Computation p. 569
- 16.8 Summary p. 581
- 16.9 References p. 582
- 17 Induction Machine Design for Variable Speed p. 585
- 17.1 Introduction p. 585
- 17.2 Power and Voltage Derating p. 587
- 17.3 Reducing the Skin Effect in Windings p. 589
- 17.4 Torque Pulsations Reduction p. 592
- 17.5 Increasing Efficiency p. 593
- 17.6 Increasing the Breakdown Torque p. 594
- 17.7 Wide Constant Power Speed Range Via Voltage Management p. 598
- 17.8 Design for High And Super-High Speed Applications p. 603
- 17.9 Sample Design Approach for Wide Constant Power Speed Range p. 610
- Solution Characterization p. 611
- 17.10 Summary p. 613
- 17.11 References p. 614
- 18 Optimization Design p. 617
- 18.1 Introduction p. 617
- 18.2 Essential Optimization Design Methods p. 620
- 18.3 The Augmented Lagrangian Multiplier Method (ALMM) p. 621
- 18.4 Sequential Unconstrained Minimization p. 622
- 18.5 A Modified Hooke-Jeeves Method p. 624
- 18.6 Genetic Algorithms p. 625
- 18.7 Summary p. 632
- 18.8 References p. 633
- 19 Three Phase Induction Generators p. 635

- 19.1 Introduction p. 635
- 19.2 Self-Excited Induction Generator (SEIG) Modeling p. 638
- 19.3 Steady State Performance of SEIG p. 640
- 19.4 The Second Order Slip Equation Model for Steady State p. 641
- 19.5 Steady State Characteristics of SEIG for Given Speed And Capacitor p. 650
- 19.6 Parameter Sensitivity in SEIG Analysis p. 651
- 19.7 Pole Changing Seigs p. 652
- 19.8 Unbalanced Steady State Operation Of SEIG p. 652
- 19.9 Transient Operation Of SEIG p. 659
- 19.10 SEIG Transients with Induction Motor Load p. 661
- 19.11 Parallel Operation of Seigs p. 663
- 19.12 The Doubly-Fed IG Connected to the Grid p. 665
- 19.13 Summary p. 671
- 19.14 References p. 672
- 20 Linear Induction Motors p. 675
- 20.1 Introduction p. 675
- 20.2 Classifications and Basic Topologies p. 678
- 20.3 Primary Windings p. 680
- 20.4 Transverse Edge Effect in Double-Sided LIM p. 682
- 20.5 Transverse Edge Effect in Single-Sided LIM p. 690
- 20.6 A Technical Theory of LIM Longitudinal End Effects p. 692
- 20.7 Longitudinal End-Effect Waves and Consequences p. 694
- 20.8 Secondary Power Factor and Efficiency p. 699
- 20.9 The Optimum Goodness Factor p. 700
- 20.10 Linear Flat Induction Actuators p. 701
- 20.11 Tubular LIAs p. 711
- 20.12 Short-Secondary Double-Sided LIAs p. 717
- 20.13 Linear Induction Motors for Urban Transportation p. 718
- 20.14 Transients and Control of LIMs p. 722
- 20.15 Electromagnetic Induction Launchers p. 723
- 20.16 Summary p. 725
- 20.17 Selected References p. 726
- 21 Super-High Frequency Models and Behaviour of IMs p. 729
- 21.1 Introduction p. 729
- 21.2 Three High Frequency Operation Impedances p. 731
- 21.3 The Differential Impedance p. 732
- 21.4 Neutral and Common Mode Impedance Models p. 736
- 21.5 The Super-High Frequency Distributed Equivalent Circuit p. 739
- 21.6 Bearing Currents Caused by PWM Inverters p. 743
- 21.7 Ways to Reduce PWM Inverter Bearing Currents p. 747
- 21.8 Summary p. 748
- 21.9 References p. 750
- 22 Testing of Three-Phase IMs p. 753
- 22.1 Loss Segregation Tests p. 753
- 22.2 Efficiency Measurements p. 764
- 22.3 The Temperature-Rise Test Via Forward Shortcircuit (FSC) Method p. 775

- 22.4 Parameter Estimation Tests p. 781
- 22.5 Noise and Vibration Measurements: From No-Load to Load p. 803
- 22.6 Summary p. 808
- 22.7 References p. 812
- 23 Single-Phase Induction Machines: The Basics p. 815
- 23.1 Introduction p. 815
- 23.2 Split-Phase Induction Motors p. 816
- 23.3 Capacitor Induction Motors p. 816
- 23.4 The Nature of Stator-Produced Airgap Field p. 823
- 23.5 The Fundamental M.M.F. and Its Elliptic Wave p. 826
- 23.6 Forward-Backward M.M.F. Waves p. 827
- 23.7 The Symmetrical Components General Model p. 828
- 23.8 The d-q Model p. 831
- 23.9 The d-q Model Of Star Steinmetz Connection p. 833
- 23.10 Summary p. 835
- 23.11 References p. 837
- 24 Single-Phase Induction Motors: Steady State p. 839
- 24.1 Introduction p. 839
- 24.2. Steady State Performance with Open Auxiliary Winding p. 839
- 24.3 The Split Phase and The Capacitor IM: Currents And Torque p. 845
- 24.4 Symmetrization Conditions p. 851
- 24.5 Starting Torque and Current Inquiries p. 853
- 24.6 Typical Motor Characteristic p. 856
- 24.7 Non-Orthogonal Stator Windings p. 858
- 24.8 Symmetrisation Conditions for Non-Orthogonal Windings p. 861
- 24.9 M.M.F. Space Harmonic Parasitic Torques p. 868
- 24.10 Torque Pulsations p. 870
- 24.11 Inter-Bar Rotor Currents p. 870
- 24.12 Voltage Harmonics Effects p. 871
- 24.13 The Doubly Tapped Winding Capacitor IM p. 873
- 24.14 Summary p. 878
- 24.15 References p. 881
- 25 Single-Phase IM Transients p. 883
- 25.1 Introduction p. 883
- 25.2 The d-q Model Performance in Stator Coordinates p. 884
- 25.3 Starting Transients p. 888
- 25.4 The Multiple Reference Model for Transients p. 890
- 25.5 Including the Space Harmonics p. 891
- 25.6 Summary p. 892
- 25.7 References p. 893
- 26 Single-Phase Induction Generators p. 895
- 26.1 Introduction p. 895
- 26.2 Steady State Model and Performance p. 896
- 26.3 The d-q Model For Transients p. 901
- 26.4 Expanding the Operation Range with Power Electronics p. 903
- 26.5 Summary p. 904

- 26.6 References p. 905
- 27 Single-Phase IM Design p. 907
- 27.1 Introduction p. 907
- 27.2 Sizing the Stator Magnetic Circuit p. 908
- 27.3 Sizing the Rotor Magnetic Circuit p. 912
- 27.4 Sizing the Stator Windings p. 913
- 27.5 Resistances and Leakage Reactances p. 918
- 27.6 The Magnetization Reactance  $X_{m[m]}$  p. 922
- 27.7 The Starting Torque and Current p. 922
- 27.8 Steady State Performance Around Rated Power p. 923
- 27.9 Guidelines for a Good Design p. 925
- 27.10 Optimization Design Issues p. 926
- 27.11 Summary p. 930
- 27.12 References p. 931
- 28 Single-Phase IM Testing p. 933
- 28.1 Introduction p. 933
- 28.2 Loss Segregation the Split Phase and Capacitor Start IMs p. 935
- 28.3 The Case of Closed Rotor Slots p. 940
- 28.4 Loss Segregation the Permanent Capacitor IM p. 941
- 28.5 Speed (slip) Measurements p. 942
- 28.6 Load Testing p. 943
- 28.7 Complete Torque-Speed Curve Measurements p. 943
- 28.8 Summary p. 945
- 28.9 References p. 946