

- Preface p. xiii
- I Introduction p. 1
- 1 Fusion Welding Processes p. 3
- 1.1 Overview p. 3
- 1.2 Oxyacetylene Welding p. 7
- 1.3 Shielded Metal Arc Welding p. 11
- 1.4 Gas-Tungsten Arc Welding p. 13
- 1.5 Plasma Arc Welding p. 16
- 1.6 Gas-Metal Arc Welding p. 19
- 1.7 Flux-Core Arc Welding p. 22
- 1.8 Submerged Arc Welding p. 22
- 1.9 Electroslag Welding p. 24
- 1.10 Electron Beam Welding p. 27
- 1.11 Laser Beam Welding p. 29
- References p. 33
- Further Reading p. 34
- Problems p. 34
- 2 Heat Flow in Welding p. 37
- 2.1 Heat Source p. 37
- 2.2 Analysis of Heat Flow in Welding p. 47
- 2.3 Effect of Welding Parameters p. 53
- 2.4 Weld Thermal Simulator p. 58
- References p. 60
- Further Reading p. 62
- Problems p. 62
- 3 Chemical Reactions in Welding p. 65
- 3.1 Overview p. 65
- 3.2 Gas-Metal Reactions p. 68
- 3.3 Slag-Metal Reactions p. 82
- References p. 92
- Further Reading p. 95
- Problems p. 95
- 4 Fluid Flow and Metal Evaporation in Welding p. 97
- 4.1 Fluid Flow in Arcs p. 97
- 4.2 Fluid Flow in Weld Pools p. 103
- 4.3 Metal Evaporation p. 114
- 4.4 Active Flux GTAW p. 116
- References p. 117
- Further Reading p. 119
- Problems p. 120
- 5 Residual Stresses, Distortion, and Fatigue p. 122
- 5.1 Residual Stresses p. 122
- 5.2 Distortion p. 126
- 5.3 Fatigue p. 131
- 5.4 Case Studies p. 137
- References p. 140

- Further Reading p. 141
- Problems p. 141
- II The Fusion Zone p. 143
- 6 Basic Solidification Concepts p. 145
- 6.1 Solute Redistribution during Solidification p. 145
- 6.2 Solidification Modes and Constitutional Supercooling p. 155
- 6.3 Microsegregation and Banding p. 160
- 6.4 Effect of Cooling Rate p. 163
- 6.5 Solidification Path p. 166
- References p. 167
- Further Reading p. 168
- Problems p. 169
- 7 Weld Metal Solidification I: Grain Structure p. 170
- 7.1 Epitaxial Growth at Fusion Boundary p. 170
- 7.2 Nonepitaxial Growth at Fusion Boundary p. 172
- 7.3 Competitive Growth in Bulk Fusion Zone p. 174
- 7.4 Effect of Welding Parameters on Grain Structure p. 174
- 7.5 Weld Metal Nucleation Mechanisms p. 178
- 7.6 Grain Structure Control p. 187
- References p. 195
- Further Reading p. 197
- Problems p. 197
- 8 Weld Metal Solidification II: Microstructure within Grains p. 199
- 8.1 Solidification Modes p. 199
- 8.2 Dendrite and Cell Spacing p. 204
- 8.3 Effect of Welding Parameters p. 206
- 8.4 Refining Microstructure within Grains p. 209
- References p. 213
- Further Reading p. 213
- Problems p. 214
- 9 Post-Solidification Phase Transformations p. 216
- 9.1 Ferrite-to-Austenite Transformation in Austenitic Stainless Steel Welds p. 216
- 9.2 Austenite-to-Ferrite Transformation in Low-Carbon, Low-Alloy Steel Welds p. 232
- References p. 239
- Further Reading p. 241
- Problems p. 241
- 10 Weld Metal Chemical Inhomogeneities p. 243
- 10.1 Microsegregation p. 243
- 10.2 Banding p. 249
- 10.3 Inclusions and Gas Porosity p. 250
- 10.4 Inhomogeneities Near Fusion Boundary p. 252
- 10.5 Macrosegregation in Bulk Weld Metal p. 255
- References p. 260
- Further Reading p. 261
- Problems p. 261
- 11 Weld Metal Solidification Cracking p. 263

- 11.1 Characteristics, Cause, and Testing p. 263
- 11.2 Metallurgical Factors p. 268
- 11.3 Mechanical Factors p. 284
- 11.4 Reducing Solidification Cracking p. 285
- 11.5 Case Study: Failure of a Large Exhaust Fan p. 295
- References p. 296
- Further Reading p. 299
- Problems p. 299
- III The Partially Melted Zone p. 301
- 12 Formation of the Partially Melted Zone p. 303
- 12.1 Evidence of Liquation p. 303
- 12.2 Liquation Mechanisms p. 304
- 12.3 Directional Solidification of Liquefied Material p. 314
- 12.4 Grain Boundary Segregation p. 314
- 12.5 Grain Boundary Solidification Modes p. 316
- 12.6 Partially Melted Zone in Cast Irons p. 318
- References p. 318
- Problems p. 319
- 13 Difficulties Associated with the Partially Melted Zone p. 321
- 13.1 Liquation Cracking p. 321
- 13.2 Loss of Strength and Ductility p. 328
- 13.3 Hydrogen Cracking p. 328
- 13.4 Remedies p. 330
- References p. 336
- Problems p. 338
- IV The Heat-Affected Zone p. 341
- 14 Work-Hardened Materials p. 343
- 14.1 Background p. 343
- 14.2 Recrystallization and Grain Growth in Welding p. 347
- 14.3 Effect of Welding Parameters and Process p. 349
- References p. 351
- Further Reading p. 352
- Problems p. 352
- 15 Precipitation-Hardening Materials I: Aluminum Alloys p. 353
- 15.1 Background p. 353
- 15.2 Al-Cu-Mg and Al-Mg-Si Alloys p. 359
- 15.3 Al-Zn-Mg Alloys p. 367
- 15.4 Friction Stir Welding of Aluminum Alloys p. 370
- References p. 371
- Further Reading p. 372
- Problems p. 372
- 16 Precipitation-Hardening Materials II: Nickel-Base Alloys p. 375
- 16.1 Background p. 375
- 16.2 Reversion of Precipitate and Loss of Strength p. 379
- 16.3 Postweld Heat Treatment Cracking p. 384
- References p. 390

- Further Reading p. 392
- Problems p. 392
- 17 Transformation-Hardening Materials: Carbon and Alloy Steels p. 393
- 17.1 Phase Diagram and CCT Diagrams p. 393
- 17.2 Carbon Steels p. 396
- 17.3 Low-Alloy Steels p. 404
- 17.4 Hydrogen Cracking p. 410
- 17.5 Reheat Cracking p. 418
- 17.6 Lamellar Tearing p. 422
- 17.7 Case Studies p. 425
- References p. 427
- Further Reading p. 429
- Problems p. 430
- 18 Corrosion-Resistant Materials: Stainless Steels p. 431
- 18.1 Classification of Stainless Steels p. 431
- 18.2 Austenitic Stainless Steels p. 433
- 18.3 Ferritic Stainless Steels p. 446
- 18.4 Martensitic Stainless Steels p. 449
- 18.5 Case Study: Failure of a Pipe p. 451
- References p. 452
- Further Reading p. 453
- Problems p. 454
- Index p. 455