

Table of contents provided by Syndetics

- **Preface** (p. xvii)
- **1 Definition and Importance of Corrosion** (p. 1)
- **1.1 Definition of Corrosion** (p. 1)
- **1.1.1 Corrosion Science and Corrosion Engineering** (p. 1)
- **1.2 Importance of Corrosion** (p. 2)
- **1.3 Risk Management** (p. 5)
- **1.4 Causes of Corrosion** (p. 6)
- **1.4.1 Change in Gibbs Free Energy** (p. 6)
- **1.4.2 Pilling-Bedworth Ratio** (p. 6)
- **References** (p. 6)
- **General References** (p. 7)
- **Problems** (p. 7)
- **2 Electrochemical Mechanisms** (p. 9)
- **2.1 The Dry-Cell Analogy and Faraday's Law** (p. 9)
- **2.2 Definition of Anode and Cathode** (p. 11)
- **2.3 Types of Cells** (p. 13)
- **2.4 Types of Corrosion Damage** (p. 15)
- **References** (p. 18)
- **General References** (p. 19)
- **Problems** (p. 19)
- **3 Thermodynamics: Corrosion Tendency and Electrode Potentials** (p. 21)
- **3.1 Change of Gibbs Free Energy** (p. 21)
- **3.2 Measuring the Emf of a Cell** (p. 22)
- **3.3 Calculating the Half-Cell Potential-The Nernst Equation** (p. 22)
- **3.4 The Hydrogen Electrode and the Standard Hydrogen Scale** (p. 24)
- **3.5 Convention of Signs and Calculation of Emf** (p. 25)
- **3.6 Measurement of pH** (p. 28)
- **3.7 The Oxygen Electrode and Differential Aeration Cell** (p. 28)
- **3.8 The Emf and Galvanic Series** (p. 30)
- **3.9 Liquid Junction Potentials** (p. 33)
- **3.10 Reference Electrodes** (p. 34)
- **3.10.1 Calomel Reference Electrode** (p. 35)
- **3.10.2 Silver-Silver Chloride Reference Electrode** (p. 36)
- **3.10.3 Saturated Copper-Copper Sulfate Reference Electrode** (p. 36)
- **References** (p. 37)
- **General References** (p. 38)
- **Problems** (p. 38)
- **Answers to Problems** (p. 40)
- **4 Thermodynamics: Pourbaix Diagrams** (p. 43)
- **4.1 Basis of Pourbaix Diagrams** (p. 43)
- **4.2 Pourbaix Diagram for Water** (p. 44)
- **4.3 Pourbaix Diagram for Iron** (p. 45)
- **4.4 Pourbaix Diagram for Aluminum** (p. 47)
- **4.5 Pourbaix Diagram for Magnesium** (p. 48)

- **4.6 Limitations of Pourbaix Diagrams** (p. 49)
- **References** (p. 50)
- **General References** (p. 50)
- **Problems** (p. 50)
- **Answers to Problem** (p. 51)
- **5 Kinetics: Polarization and Corrosion Rates** (p. 53)
- **5.1 Polarization** (p. 53)
- **5.2 The Polarized Cell** (p. 54)
- **5.3 How Polarization Is Measured** (p. 56)
- **5.3.1 Calculation of IR Drop in an Electrolyte** (p. 58)
- **5.4 Causes of Polarization** (p. 58)
- **5.5 Hydrogen Overpotential** (p. 63)
- **5.6 Polarization Diagrams of Corroding Metals** (p. 66)
- **5.7 Influence of Polarization on Corrosion Rate** (p. 68)
- **5.8 Calculation of Corrosion Rates from Polarization Data** (p. 71)
- **5.9 Anode-Cathode Area Ratio** (p. 73)
- **5.10 Electrochemical Impedance Spectroscopy** (p. 75)
- **5.11 Theory of Cathodic Protection** (p. 77)
- **References** (p. 79)
- **General References** (p. 80)
- **Problems** (p. 80)
- **Answers to Problems** (p. 82)
- **6 Passivity** (p. 83)
- **6.1 Definition** (p. 83)
- **6.2 Characteristics of Passivation and the Flade Potential** (p. 84)
- **6.3 Behavior of Passivators** (p. 88)
- **6.3.1 Passivation of Iron by HNO₃** (p. 89)
- **6.4 Anodic Protection and Transpassivity** (p. 90)
- **6.5 Theories of Passivity** (p. 92)
- **6.5.1 More Stable Passive Films with Time** (p. 95)
- **6.5.2 Action of Chloride Ions and Passive-Active Cells** (p. 96)
- **6.6 Critical Pitting Potential** (p. 97)
- **6.7 Critical Pitting Temperature** (p. 99)
- **6.8 Passivity of Alloys** (p. 100)
- **6.8.1 Nickel-Copper Alloys** (p. 103)
- **6.8.2 Other Alloys** (p. 108)
- **6.9 Effect of Cathodic Polarization and Catalysis** (p. 108)
- **References** (p. 109)
- **General References** (p. 111)
- **Problems** (p. 112)
- **Answers to Problems** (p. 113)
- **7 Iron and Steel** (p. 115)
- **7.1 Introduction** (p. 115)
- **7.2 Aqueous Environments** (p. 116)
- **7.2.1 Effect of Dissolved Oxygen** (p. 116)
- **7.2.2 Effect of Temperature** (p. 120)

- **7.2.3 Effect of pH** (p. 120)
- **7.2.4 Effect of Galvanic Coupling** (p. 127)
- **7.2.5 Effect of Velocity on Corrosion in Natural Waters** (p. 129)
- **7.2.6 Effect of Dissolved Salts** (p. 131)
- **7.3 Metallurgical Factors** (p. 138)
 - **7.3.1 Varieties of Iron and Steel** (p. 138)
 - **7.3.2 Effects of Composition** (p. 138)
 - **7.3.3 Effect of Heat Treatment** (p. 142)
- **7.4 Steel Reinforcements in Concrete** (p. 143)
- **References** (p. 145)
- **General References** (p. 147)
- **Problems** (p. 147)
- **Answers to Problems** (p. 148)
- **8 Effect of Stress** (p. 149)
 - **8.1 Cold Working** (p. 149)
 - **8.2 Stress-Corrosion Cracking** (p. 150)
 - **8.2.1 Iron and Steel** (p. 151)
 - **8.3 Mechanism of Stress-Corrosion Cracking of Steel and Other Metals** (p. 156)
 - **8.3.1 Electrochemical Dissolution** (p. 157)
 - **8.3.2 Film-Induced Cleavage** (p. 158)
 - **8.3.3 Adsorption-Induced Localized Slip** (p. 158)
 - **8.3.4 Stress Sorption** (p. 158)
 - **8.3.5 Initiation of Stress-Corrosion Cracking and Critical Potentials** (p. 161)
 - **8.3.6 Rate of Crack Growth (Fracture Mechanics)** (p. 162)
 - **8.4 Hydrogen Damage** (p. 166)
 - **8.4.1 Mechanism of Hydrogen Damage** (p. 167)
 - **8.4.2 Effect of Metal Flaws** (p. 170)
 - **8.5 Radiation Damage** (p. 172)
 - **8.6 Corrosion Fatigue** (p. 173)
 - **8.6.1 Critical Minimum Corrosion Rates** (p. 177)
 - **8.6.2 Remedial Measures** (p. 178)
 - **8.6.3 Mechanism of Corrosion Fatigue** (p. 179)
 - **8.7 Fretting Corrosion** (p. 180)
 - **8.7.1 Mechanism of Fretting Corrosion** (p. 182)
 - **8.7.2 Remedial Measures** (p. 184)
- **References** (p. 185)
- **General References** (p. 188)
- **Problems** (p. 190)
- **Answers to Problems** (p. 190)
- **9 Atmospheric Corrosion** (p. 191)
 - **9.1 Introduction** (p. 191)
 - **9.2 Types of Atmospheres** (p. 192)
 - **9.3 Corrosion-Product Films** (p. 192)
 - **9.4 Factors Influencing Corrosivity of the Atmosphere** (p. 195)
 - **9.4.1 Particulate Matter** (p. 196)
 - **9.4.2 Gases in the Atmosphere** (p. 197)

- **9.4.3 Moisture (Critical Humidity)** (p. 199)
- **9.5 Remedial Measures** (p. 201)
- **References** (p. 202)
- **General References** (p. 203)
- **Problems** (p. 204)
- **10 Corrosion in Soils** (p. 205)
- **10.1 Introduction** (p. 205)
- **10.2 Factors Affecting the Corrosivity of Soils** (p. 206)
- **10.3 Bureau of Standards Tests** (p. 207)
- **10.3.1 Pitting Characteristics** (p. 208)
- **10.4 Stress-Corrosion Cracking** (p. 210)
- **10.5 Remedial Measures** (p. 211)
- **References** (p. 212)
- **General References** (p. 212)
- **11 Oxidation** (p. 215)
- **11.1 Introduction** (p. 215)
- **11.2 Initial Stages** (p. 216)
- **11.3 Thermodynamics of Oxidation: Free Energy-Temperature Diagram** (p. 218)
- **11.4 Protective and Nonprotective Scales** (p. 218)
- **11.4.1 Three Equations of Oxidation** (p. 220)
- **11.5 Wagner Theory of Oxidation** (p. 223)
- **11.6 Oxide Properties and Oxidation** (p. 224)
- **11.7 Galvanic Effects and Electrolysis of Oxides** (p. 227)
- **11.8 Hot Ash Corrosion** (p. 229)
- **11.9 Hot Corrosion** (p. 229)
- **11.10 Oxidation of Copper** (p. 230)
- **11.13.1 Reactive Element Effect (REE)** (p. 234)
- **11.10.1 Internal Oxidation** (p. 231)
- **11.10.2 Reaction with Hydrogen ("Hydrogen Disease")** (p. 231)
- **11.11 Oxidation of Iron and Iron Alloys** (p. 232)
- **11.12 Life Test for Oxidation-Resistant Wires** (p. 233)
- **11.13 Oxidation-Resistant Alloys** (p. 234)
- **11.13.2 Chromium-Iron Alloys** (p. 235)
- **11.13.3 Chromium-Aluminum-Iron Alloys** (p. 236)
- **11.13.4 Nickel and Nickel Alloys** (p. 236)
- **11.13.5 Furnace Windings** (p. 237)
- **References** (p. 237)
- **General References** (p. 239)
- **Problems** (p. 239)
- **Answers to Problems** (p. 240)
- **12 Stray-Current Corrosion** (p. 241)
- **12.1 Introduction** (p. 241)
- **12.2 Sources of Stray Currents** (p. 242)
- **12.3 Quantitative Damage by Stray Currents** (p. 244)
- **12.4 Detection of Stray Currents** (p. 245)
- **12.5 Soil-Resistivity Measurement** (p. 246)

- **12.6 Means for Reducing Stray-Current Corrosion** (p. 246)
- **References** (p. 247)
- **General References** (p. 247)
- **Problems** (p. 247)
- **Answers to Problems** (p. 249)
- **13 Cathodic Protection** (p. 251)
- **13.1 Introduction** (p. 251)
- **13.2 Brief History** (p. 252)
- **13.3 How Applied** (p. 253)
- **13.3.1 Sacrificial Anodes** (p. 254)
- **13.4 Combined Use with Coatings** (p. 255)
- **13.5 Magnitude of Current Required** (p. 257)
- **13.6 Anode Materials and Backfill** (p. 258)
- **13.6.1 Overprotection** (p. 259)
- **13.7 Criteria of Protection** (p. 260)
- **13.7.1 Potential Measurements** (p. 260)
- **13.7.2 Doubtful Criteria** (p. 262)
- **13.7.3 Position of Reference Electrode** (p. 262)
- **13.8 Economics of Cathodic Protection** (p. 263)
- **13.9 Anodic Protection** (p. 263)
- **References** (p. 265)
- **General References** (p. 265)
- **Problems** (p. 266)
- **Answers to Problems** (p. 267)
- **14 Metallic Coatings** (p. 269)
- **14.1 Methods of Application** (p. 269)
- **14.2 Classification of Coatings** (p. 271)
- **14.3 Specific Metal Coatings** (p. 272)
- **14.3.1 Nickel Coatings** (p. 272)
- **14.3.2 Lead Coatings** (p. 274)
- **14.3.3 Zinc Coatings** (p. 274)
- **14.3.4 Cadmium Coatings** (p. 276)
- **14.3.5 Tin Coatings** (p. 277)
- **14.3.6 Chromium-Plated Steel for Containers** (p. 279)
- **14.3.7 Aluminum Coatings** (p. 280)
- **References** (p. 281)
- **General References** (p. 282)
- **15 Inorganic Coatings** (p. 285)
- **15.1 Vitreous Enamels** (p. 285)
- **15.2 Portland Cement Coatings** (p. 286)
- **15.3 Chemical Conversion Coatings** (p. 286)
- **References** (p. 288)
- **General References** (p. 288)
- **16 Organic Coatings** (p. 289)
- **16.1 Introduction** (p. 289)
- **16.2 Paints** (p. 289)

- **16.3 Requirements for Corrosion Protection** (p. 291)
- **16.4 Metal Surface Preparation** (p. 293)
 - **16.4.1 Cleaning All Dirt, Oils, and Greases from the Surface** (p. 293)
 - **16.4.2 Complete Removal of Rust and Mill Scale** (p. 294)
- **16.5 Applying Paint Coatings** (p. 295)
 - **16.5.1 Wash Primer** (p. 296)
 - **16.5.2 Painting of Aluminum and Zinc** (p. 296)
- **16.6 Filiform Corrosion** (p. 296)
 - **16.6.1 Theory of Filiform Corrosion** (p. 298)
- **16.7 Plastic Linings** (p. 299)
- **References** (p. 300)
- **General References** (p. 301)
- **17 Inhibitors and Passivators** (p. 303)
 - **17.1 Introduction** (p. 303)
 - **17.2 Passivators** (p. 304)
 - **17.2.1 Mechanism of Passivation** (p. 304)
 - **17.2.2 Applications of Passivators** (p. 308)
 - **17.3 Pickling Inhibitors** (p. 310)
 - **17.3.1 Applications of Pickling Inhibitors** (p. 312)
 - **17.4 Slushing Compounds** (p. 313)
 - **17.5 Vapor-Phase Inhibitors** (p. 313)
 - **17.5.1 Inhibitor to Reduce Tarnishing of Copper** (p. 314)
- **References** (p. 315)
- **General References** (p. 316)
- **18 Treatment of Water and Steam Systems** (p. 317)
 - **18.1 Deaeration and Deactivation** (p. 317)
 - **18.2 Hot- and Cold-Water Treatment** (p. 321)
 - **18.2.1 Cooling Waters** (p. 322)
 - **18.3 Boiler-Water Treatment** (p. 323)
 - **18.3.1 Boiler Corrosion** (p. 323)
 - **18.3.2 Boiler-Water Treatment for Corrosion Control** (p. 326)
 - **18.3.3 Mechanisms** (p. 328)
- **References** (p. 330)
- **General References** (p. 331)
- **19 Alloying for Corrosion Resistance; Stainless Steels** (p. 333)
 - **19.1 Introduction** (p. 333)
 - **19.2 Stainless Steels** (p. 335)
 - **19.2.1 Brief History** (p. 336)
 - **19.2.2 Classes and Types** (p. 337)
 - **19.2.3 Intergranular Corrosion** (p. 343)
 - **19.2.4 Pitting and Crevice Corrosion** (p. 350)
 - **19.2.5 Stress-Corrosion Cracking and Hydrogen Cracking** (p. 354)
 - **19.2.6 Cracking of Sensitized Austenitic Alloys in Polythionic Acids** (p. 359)
 - **19.2.7 Galvanic Coupling and General Corrosion Resistance** (p. 361)
- **References** (p. 362)
- **General References** (p. 365)

- **20 Copper and Copper Alloys** (p. 367)
- **20.1 Copper** (p. 367)
- **20.1.1 Corrosion in Natural Waters** (p. 369)
- **20.2 Copper Alloys** (p. 371)
- **20.2.1 Copper-Zinc Alloys (Brasses)** (p. 371)
- **20.2.2 Dealloying/Dezincification** (p. 372)
- **20.2.3 Stress-Corrosion Cracking (Season Cracking)** (p. 374)
- **20.2.4 Condenser Tube Alloys Including Copper-Nickel Alloys** (p. 378)
- **References** (p. 379)
- **General References** (p. 381)
- **Problems** (p. 381)
- **Answers to Problems** (p. 381)
- **21 Aluminum and Aluminum Alloys** (p. 383)
- **21.1 Aluminum** (p. 383)
- **21.1.1 Clad Alloys** (p. 384)
- **21.1.2 Corrosion in Water and Steam** (p. 384)
- **21.1.3 Effect of pH** (p. 387)
- **21.1.4 Corrosion Characteristics** (p. 388)
- **21.1.5 Galvanic Coupling** (p. 392)
- **21.2 Aluminum Alloys** (p. 393)
- **21.2.1 Stress-Corrosion Cracking** (p. 394)
- **References** (p. 396)
- **General References** (p. 397)
- **22 Magnesium and Magnesium Alloys** (p. 399)
- **22.1 Introduction** (p. 399)
- **22.2 Magnesium** (p. 399)
- **22.3 Magnesium Alloys** (p. 400)
- **22.3.1 Stress-Corrosion Cracking** (p. 402)
- **22.3.2 Coatings** (p. 403)
- **22.4 Summary** (p. 404)
- **23.1 Introduction** (p. 407)
- **References** (p. 405)
- **General References** (p. 405)
- **23 Nickel and Nickel Alloys** (p. 407)
- **23.2 Nickel** (p. 408)
- **23.3 Nickel Alloys** (p. 411)
- **23.3.1 General Behavior** (p. 411)
- **23.3.2 Ni-Cu System: Alloy 400-70% Ni, 30% Cu** (p. 414)
- **23.3.3 Ni-Cr-Fe System: Alloy 600-76% Ni, 16% Cr, 7% Fe** (p. 414)
- **23.3.4 Ni-Mo System: Alloy B-60% Ni, 30% Mo, 5% Fe** (p. 415)
- **23.3.5 Ni-Cr-Fe-Mo-Cu System: Alloy G-Ni, 22% Cr, 20% Fe, 6.5% Mo, 2% Cu** (p. 416)
- **23.3.6 Ni-Cr-Mo System: Alloy C-54% Ni, 15% Cr, 16% Mo, 4% W, 5% Fe** (p. 416)
- **23.3.7 Ni-Fe-Cr System: Alloy 825-Ni, 31% Fe, 22% Cr** (p. 417)
- **References** (p. 417)
- **General References** (p. 418)

- **24 Cobalt and Cobalt Alloys** (p. 419)
- **24.1 Introduction** (p. 419)
- **24.2 Cobalt Alloys** (p. 420)
- **References** (p. 423)
- **General References** (p. 423)
- **25 Titanium** (p. 425)
- **25.1 Titanium** (p. 425)
- **25.2 Titanium Alloys** (p. 427)
- **25.3 Pitting and Crevice Corrosion** (p. 429)
- **25.4 Intergranular Corrosion and Stress-Corrosion Cracking** (p. 430)
- **References** (p. 432)
- **General References** (p. 434)
- **Problem** (p. 434)
- **26 Zirconium** (p. 435)
- **26.1 Introduction** (p. 435)
- **26.2 Zirconium Alloys** (p. 436)
- **26.3 Behavior in Hot Water and Steam** (p. 437)
- **References** (p. 439)
- **General References** (p. 440)
- **27 Tantalum** (p. 441)
- **27.1 Introduction** (p. 441)
- **27.2 Corrosion Behavior** (p. 441)
- **References** (p. 443)
- **General Reference** (p. 443)
- **28 Lead** (p. 445)
- **28.1 Introduction** (p. 445)
- **28.2 Corrosion Behavior of Lead and Lead Alloys** (p. 446)
- **28.2.1 Lead-Acid Battery** (p. 447)
- **28.3 Summary** (p. 448)
- **References** (p. 449)
- **General References** (p. 449)
- **29 Appendix** (p. 451)
- **29.1 Activity and Activity Coefficients of Strong Electrolytes** (p. 451)
- **29.2 Derivation of Stern-Geary Equation for Calculating Corrosion Rates from Polarization Data Obtained at Low Current Densities** (p. 456)
- **29.2.1 The General Equation** (p. 458)
- **29.3 Derivation of Equation Expressing the Saturation Index of a Natural Water** (p. 461)
- **29.4 Derivation of Potential Change along a Cathodically Protected Pipeline** (p. 467)
- **29.5 Derivation of the Equation for Potential Drop along the Soil Surface Created by Current Entering or Leaving a Buried Pipe** (p. 469)
- **29.6 Derivation of the Equation for Determining Resistivity of Soil by Four-Electrode Method** (p. 470)
- **29.7 Derivation of the Equation Expressing Weight Loss by Fretting Corrosion** (p. 471)
- **29.8 Conversion Factors** (p. 474)

- **29.8.1 Additional Conversion Factors** (p. 475)
- **29.8.2 Current Density Equivalent to a Corrosion Rate of 1 gmd** (p. 475)
- **29.9 Standard Potentials** (p. 476)
- **29.10 Notation and Abbreviations** (p. 476)
- **References** (p. 478)
- **Index** (p. 479)